



RPL1000
Monitor Repair Parts

LIST PRICES
Effective: April 14, 2025
Revised: April 3, 2025



Ord. No.	List Price	Ord. No.	List Price	Ord. No.	List Price	Ord. No.	List Price
1.5WP75	76.97	CD90	36.22	DRPT10	137.42	HF30	8.32
10-174ALFFRO	134.21	C80FFRO	71.41	DRPT2	100.86	HF33	8.07
10WP75	114.70	C80M	50.78	DRPT2.5	94.69	HF50	767.73
1WP75	75.70	CA387M	119.46	DRPT3	106.73	HF57	5.54
2.5WP75	79.35	CF90	37.18	DRPT4	123.39	HF61A	28.33
2WP75	78.14	CJ90	52.54	DRPT6	114.84	KH320	4.73
3WP75	80.48	CXF1	60.34	DRPT7	120.23	KP145S	45.87
4WP75	82.90	DP11	14.55	DRPT8	150.52	L148	89.55
5WP75	85.23	DP12	15.73	E42S	0.33	L168	95.69
6WP75	87.66	DP134	100.13	E49N	2.62	LK4S	73.10
7WP75	90.08	DP16	112.33	E80	4.29	MP36	64.54
8WP75	92.43	DP17	4.29	EP54	22.23	NA115	8.59
AB10	30.82	DP18	93.86	FM7S	2.73	NA17	121.23
AB5	14.25	DP195	35.81	G150	53.89	NA233	419.57
AB5.5	13.73	DP196	46.66	G18.4X3	193.38	NA234	468.87
AB6	13.73	DP197	40.93	G18.6X4	313.84	NA31	94.91
AB7	13.73	DP20	4.15	GI11T	4.98	NA31P	123.95
AB8	12.31	DP202P	309.81	GO21	5.84	NA333	434.05
AG10	238.87	DP22	2.99	H211A	13.33	NA39	10.92
AG4	36.90	DP25	44.37	H215DFRO	26.41	NA40	257.24
AG5	38.40	DP26	25.09	H220DAXFRO	20.15	NA80	171.88
AG5.5	38.41	DP27	194.46	H222WMFRO	146.45	NB15	22.37
AG6	38.41	DP30	208.71	H228	6.11	NC15	17.99
AG7	65.02	DP31LF	27.56	H230AFRO	44.32	NC16	4.23
AG8	68.15	DP35	221.79	HA152	218.72	NC47	33.53
APC14	53.65	DP39	175.06	HA153	351.69	NC65	49.51
APC24	178.37	DP40	113.99	HA155	66.68	O200	237.63
APC34	65.11	DP46	14.60	HA20	60.05	O31LF	44.72
APC45	106.23	DP47	70.92	HA52	28.74	O37FRO	404.40
APC46	140.71	DP48	14.79	HA5FRO	205.68	O38FRO	149.51
APC55	249.10	DP49	4.17	HC50	996.87	O400	107.42
APC56	272.30	DP50	319.63	HC50A	2156.69	O41	4.15
APC7	5.28	DP52	367.03	HD140	987.63	O42	12.03
APC7S	7.91	DP53FRO	281.26	HD140A	1240.76	O43	37.18
BEZ4	46.78	DP56	324.78	HD156FRO	258.09	O460	37.38
BX220	3.83	DP57	139.82	HD160	480.54	O50	152.84
C00FRO	13.83	DP58	1698.01	HD189	82.44	O52	228.18
C125FW	242.10	DP59	253.57	HD190	55.68	O53	14.55
C125W	263.16	DP60P	174.25	HD34	9.06	O54	15.95
C20FW	293.31	DP61	94.04	HD5	221.96	O6	122.96
C2FW	167.98	DP62	17.91	HD54	56.66	O7	677.44
C210	56.16	DP66P	296.83	HD59	6.52	O80	28.74
C260FRO	76.50	DP68P	314.70	HD64	47.81	O81	11.03
C311	76.50	DP70	8.07	HD67	23.61	O9	111.34
C5125BW	325.81	DP72	399.68	HD69	52.13	ORH10	3.91
C5BW	251.33	DP76	48.49	HD70	4.15	PA138TLF	47.18
C6125BW	297.15	DP90	97.18	HD71	20.44	PA140TLF	93.36
C6BW	273.26	DRPT1	85.82	HD71G	16.51	PA140TPLF	90.37
C6W	166.47	DRPT1.5	89.30	HD90	70.64	PA141TLFFRO	133.91
CA82F	69.29			HF153	255.71	PA142TLFFRO	187.45



RPL1000
Monitor Repair Parts

LIST PRICES
Effective: April 14, 2025



Ord. No.	List Price	Ord. No.	List Price	Ord. No.	List Price	Ord. No.	List Price
PA143TLFFRO	164.57	PL221	63.30	PS101	2.78	PS262	12.43
PA144ATLF	33.02	PL225	64.37	PS110	13.42	PS263	16.51
PA144T	18.67	PL24	150.25	PS111	6.24	PS265	18.01
PA154	35.00	PL3	12.08	PS111S	8.73	PS27	3.27
PA155MLF	264.80	PL304	75.18	PS116	40.24	PS282LF	108.57
PA155MT	270.21	PL304.2	79.06	PS120	25.81	PS29	4.19
PA159	50.98	PL304.2BLF	149.99	PS123	8.36	PS341	320.46
PA709	6.90	PL304BLF	143.65	PS132	3.37	PS342	28.52
PC127	3.66	PL305	69.45	PS132S	4.11	PS350	547.51
PC286	3.88	PL305BLF	144.80	PS134	90.08	PS365S	131.99
PC286S	4.25	PL305.2	82.56	PS135	98.47	PS374	81.26
PC287	7.45	PL305.2BLF	155.12	PS136	104.92	PS375	88.88
PC288	4.50	PL305.62	40.77	PS139D	12.95	PS376	105.59
PC330	45.04	PL306	76.59	PS151	174.19	PS376.6	110.54
PC332	5.18	PL306.2	73.81	PS156	226.43	PS377	106.14
PC335	77.44	PL306.2BLF	152.90	PS164	39.55	PS421	10.59
PC335A	164.78	PL306BLF	149.03	PS165	43.07	PS422	280.50
PC371	6.12	PL34	33.23	PS166	67.05	PS423	10.39
PC386	4.29	PL40	8.58	PS166.6	63.35	PS425	14.17
PC415	4.29	PL49	172.41	PS167	70.14	PS427	27.34
PC417	4.42	PL4S	7.83	PS168	145.45	PS429	30.17
PC42	530.52	PL50	18.30	PS170	168.11	PS430	36.15
PC429	32.81	PL83	64.88	PS171	3.54	PS44LF	122.37
PC433	4.00	PL84	56.85	PS178	158.69	PS46	6.76
PC433S	7.34	PL8401	219.45	PS181	5.72	PS464FRO	23.31
PC434S	2.37	PL84012	260.39	PS182	18.68	PS465FRO	29.84
PC45	11.20	PL84012BLF	299.75	PS184	64.88	PS466FRO	58.65
PC95	10.02	PL8401BLF	293.75	PS185	74.14	PS535	0.57
PH1FRO	75.82	PL8431	229.62	PS186	84.00	PS544	45.85
PH2FRO	119.67	PL84312	266.15	PS186.6	103.39	PS5441	48.37
PH50	32.93	PL85	60.40	PS187	104.39	PS5441P	37.80
PH8B	10.19	PL8501	227.16	PS188	189.89	PS5451	49.09
PH8N	3.83	PL85012	265.62	PS189	188.05	PS5451P	51.02
PJ50	3.00	PL85012BLF	326.24	PS194	10.58	PS5461	52.55
PJ50S	8.12	PL8501BLF	272.31	PS195	12.99	PS5461P	52.55
PK13	4.42	PL8521	228.56	PS196	15.04	PS5471	74.16
PK29	25.19	PL86	48.41	PS196.6	14.65	PS550S	2.48
PK97	3.44	PL8601	236.95	PS197	19.26	PS564	7.40
PL106	194.65	PL86012	273.49	PS198	33.44	PS565	9.53
PL10S	14.35	PL86012BLF	274.48	PS199	4.08	PS566A	9.53
PL150B	13.70	PL8601BLF	305.17	PS2	3.47	PS567	14.84
PL151B	17.61	PL8621	231.71	PS216	100.87	PS574A	12.37
PL2	16.31	PL86212	270.00	PS217	159.03	PS575A	12.54
PL21	29.13	PL87	33.11	PS218	427.35	PS576A	12.54
PL214	57.70	PL98	189.73	PS219	6.65	PS577A	14.32

PL215A	62.80	PN13	8.65	PS220	7.19	PS585	4.44
PL216A	65.25	PR1ALF	71.41	PS221	4.24	PS585A	9.72
PL21S	7.00	PR3	4.23	PS221S	17.46	PS585B	5.45



RPL1000
Monitor Repair Parts

LIST PRICES
Effective: April 14, 2025



Ord. No.	List Price	Ord. No.	List Price	Ord. No.	List Price	Ord. No.	List Price
PS586	3.03	UC285	137.43	UJ7	194.75	UR72	362.59
PS594	82.82	UC288	92.40	UJ8	78.29	UR7A	#N/A
PS594.5	86.34	UC289	128.55	UJ80	27.40	UR850	2879.01
PS595	82.82	UC291	1196.28	UJ85	398.92	US15A	306.69
PS595.5	139.73	UC294	863.96	UJ90	74.19	US72	514.11
PS596	81.20	UC334	1447.68	UK15	65.31	WA13	21.90
PS5961.2	92.16	UC391	1701.88	UK188	8.93	WA14C	#N/A
PS59651.2	92.69	UC491FRO	1586.05	UK251	9.21	WA8	403.59
PS5971.2	106.10	UC66	2.96	UK254X29	197.68	WA9	161.01
PS9	15.06	UC670	1084.42	UK308	82.37	WBAG	49.57
PS92S	5.50	UE105	147.02	UK60E	4878.79	WBAG1	58.21
PS93	3.71	UE196	94.20	UK671	382.79	WBAG3	152.81
PS93S	4.78	UE197	55.76	UK673	633.27	WBAG4	163.45
PS94S	7.62	UE234	858.23	UK674	685.16	WBAG5	491.98
SE2115N71	1.88	UE34	754.90	UK693	1027.59	WBAG6	58.21
SE2115N90	1.88	UE383D	980.06	UK7	248.96	WBAG7	67.02
SE2224N70	1.55	UE44	733.89	UK72	220.90	WE1	15.05
SE2429E70	6.78	UE560	865.26	UK7M	192.54	WE1P	8.45
SE2441E70	8.20	UE560D	1421.19	UK850	1069.87	YB60	583.33
SE2446B	76.92	UE560M	1209.74	UK94	238.70	YB9	745.38
SW11	38.96	UE96	108.11	UL102	455.72	YC218	210.29
SW33	15.55	UG15	54.00	UL15	126.51	YC225	3.97
SW54	3.36	UG191	7.10	UL168	370.66	YC239	47.49
SW68	3.56	UG260	196.77	UL254	631.55	YC240C	368.61
THF1ATLF	83.04	UG333A	399.06	UL97	1006.15	YC241	124.36
TOR1	4.16	UG335	197.18	UL97P	1006.15	YH175	5.56
TOR125	3.17	UG3A	3383.29	UM140	10.42	YH7575	6.03
TP82	16.78	UG54	16.81	UM15	149.72	ZA1	53.05
TX15	3.09	UG54G	24.39	UM60E	7337.85	ZA12	252.59
TX31	5.04	UG7BH	307.73	UM7	220.35	ZA19	36.52
UB15	15.55	UG7SPECIAL	278.88	UM72	258.00	ZA197	31.27
UB163	572.61	UH15	41.55	UM850	1960.78	ZA198	12.18
UB17	3.72	UH85	107.78	UN120	10.76	ZA20	221.67
UB17S	2.41	UJ140	4812.09	UN122	3.45	ZA201	195.46
UB190	83.67	UJ144	1022.89	UN15	152.84	ZA203	637.75
UB201	5.51	UJ145	230.62	UN170	72.28	ZA204	36.34
UB334	834.40	UJ15	62.00	UN243	4.07	ZA205	17.29
UB450	809.80	UJ154	18.00	UN243W	2.04	ZA21	11.01
UB450D	1147.69	UJ155	11.78	UN320A	#N/A	ZA215	39.09
UB450M	986.38	UJ174	671.64	UN7	329.06	ZA22	52.05
UB83	616.32	UJ175	402.56	UN72	280.25	ZA220	9.42
UB88	85.78	UJ176	446.89	UN73S	19.89	ZA222	11.01

UB89	85.78	UJ177	12.45	UN81	6.45	ZA223A	118.25
UC129	177.35	UJ177S	25.06	UN850	3299.84	ZA23	14.82
UC139	7.10	UJ178	6.89	UQ15A	248.17	ZA230	556.05
UC15	26.75	UJ32	698.64	UQ66	889.87	ZA231	193.61
UC160	270.91	UJ32X22	3047.95	UQ72	362.59	ZA24	302.29
UC254	729.53	UJ50	129.77	UR15A	288.98	ZA240	268.50



RPL1000
Monitor Repair Parts

LIST PRICES
Effective: April 14, 2025



Ord. No.	List Price
ZA246	15.15
ZA26	8.86
ZA28	144.76
ZA333	120.81
ZA406	291.86
ZA506	221.75
ZA512	48.34
ZA513	59.54
ZA514	53.43
ZA516	39.49
ZA517	22.99
ZA524	67.64
ZA526	105.26
ZA527	7.10
ZA532	3.76
ZA6	17.12
ZA602	7.67
ZA61	106.27
ZA63	19.24
ZA64	2.53
ZA70	4.94
ZA8	947.48
ZA80	3.53
ZA94	58.74

Ord. No.	List Price
----------	------------

Ord. No.	List Price
----------	------------

Ord. No	List Price
---------	------------

